BIEE-020

B.Tech. IN ELECTRICAL ENGINEERING Term-End Examination June, 2012 BIEE-020 : ELECTRICAL MACHINES AND ELECTRONICS

Time : 3 hours

Maximum Marks: 70

Note: Answer any seven questions in all.

- Explain how do you measure 3-phase power and 10 Power factor angle with two wattmeters. Draw phasor diagrams.
- 2. (a) Draw and explain equivalent circuit of $1-\phi$ 5 transformer.
 - (b) A 50 kVA transformer has an efficiency of 5 98% at full load, 0.8 p.f and an efficiency of 96.9% at $\frac{1}{4}$ full load, unity p.f. Determine the iron loss and full load copper loss.
- 3. (a) Draw the phase diagram of a single phase 5 transformer under loaded condition with logging power factor.
 - (b) Derive the condition for maximum 5 efficiency of a transformer.

BIEE-020

1

P.T.O

4.	in 3 phase induction motors.		10
5.	Explain why single phase induction motor is not self starting and describe the different methods of its starting.		10
6.	Draw and explain volt-ampere characteristic and Switching characteristic of an SCR.		10
7.	Wha circu	What is a chopper? Draw and explain a chopper circuit with waveforms.	
8.	Explain in detail the factors affecting selection of motors for industrial use.		10
9.	(a)	A delta load of Z_{AB} =52 $\angle 45^{\circ} \Omega$;	5
		$Z_{BC} = 52 \ \angle -30^{\circ} \Omega$ and $Z_{CA} = 10 \ \angle 0^{\circ} \Omega$ are connected to a 230 V, 3 phase source. Find the magnitude of the line currents, when the phase sequence is ABC.	
	(b)	Determine the resistance between the point x and y for the network given below.	5

y

2

1Ω

 1Ω

2Ω

10. Write short note on *any two* of the following : 2x5=10

- (a) Welding Transformer
- (b) Slip Torque characteristic of 3-φ induction motor
- (c) Control of dc motors by power electronic devices.