

**B.Tech. MECHANICAL ENGINEERING
(COMPUTER INTEGRATED
MANUFACTURING) /
B.Tech. AEROSPACE ENGINEERING (BTAE) /
BTMEVI**

01190

Term-End Examination

June, 2014

BME-018 : ENGINEERING MATERIALS

Time : 3 hours

Maximum Marks : 70

Note : *Answer any seven questions. All questions carry equal marks. Use of scientific calculator is permitted.*

1. (a) Derive the relationship between True strain and Engineering strain. What is Resilience ? Why is it important for spring material ?
- (b) Suggest one suitable material for each of the following purposes, with justifications :
 - (i) File cabinet
 - (ii) Chisel
 - (iii) Water tub
 - (iv) Manhole cover
 - (v) Glass cutter

5+5

2. (a) State the advantages of Normalising and Annealing.
- (b) What is Tempering ? Is it essential for high carbon steel after quenching ? 5+5
3. (a) Explain a Chain Polymerisation reaction. What is the Degree of Polymerisation ?
- (b) Differentiate between Ceramics and Glass, with examples. What is the Glass Transition Temperature ? 5+5
4. (a) Name two important ceramic insulators with their properties.
- (b) Find the Young's Modulus of a brass rod of diameter 25 mm and of length 250 mm, which is subjected to a tensile load of 50 kN, when the extension of the rod is equal to 0.30 mm. 5+5
5. (a) Distinguish between paramagnetism and ferromagnetism. Explain the mechanics involving electron spins.
- (b) What do you understand by hardness of a grinding wheel ? What are voids in grinding wheel ? What role do they play in functioning of grinding wheel ? 5+5

6. (a) What is meant by thermal shock ? Why do refractory materials have low thermal shock resistance ?
- (b) Describe aluminium alloys commonly used for engineering applications. Give their properties and applications. 5+5
7. (a) Describe different methods of surface hardening. Give examples of surface hardened parts.
- (b) Differentiate between Austempering and Martempering. 5+5
8. (a) Describe the following phases in iron-carbon phase diagram :
- (i) Pearlite
 - (ii) Ferrite
 - (iii) Cementite
 - (iv) Austenite
 - (v) Ledeburite
- (b) A hammer weighing 50 N at the end of a swinging arm of length 800 mm is lifted to a height of 1600 mm from the level of Charpy test specimen. With what speed will the hammer strike the specimen ? If the hammer is released and no specimen is placed in its path, the hammer raises to a height of 1475 mm. How much energy is lost in friction and air resistance ? 5+5

9. (a) Define the term Wear. What are the factors influencing wear ?

(b) A piece of copper originally 305 mm long is pulled in tension with a stress of 276 MPa. If deformation is entirely elastic, what will be the resultant elongation ?

Take E for copper = 11.0×10^4 MPa. 5+5

10. (a) A composite is made of alternate layers of 62% E-glass and 38% epoxy resin. If moduli of elasticity of E-glass and epoxy are respectively 75 GPa and 4 GPa, find modulus of elasticity of the laminated composite under isostrain and isostress conditions.

(b) Describe in brief the important properties of lubricants. 5+5
