## CERTIFICATE IN SHOE UPPER CUTTING

# Term-End Examination December, 2011

00112

### **OET-012: MATERIAL COSTING AND CUTTING**

Time : 2 hours			Maximum Marks: 100			
Note: All questions are compulsory.						
1.	Fill ir	n the blanks :	1x10=10			
	(a)	In goat leathernecessary before cutting.	matching is			
	(b)	Normally 15 mm allowand purpose.	ce is given for the			
	(c)	Defects of leather can and				
	(d)	Coated fabric is genera material.	_			
	(e)	defect is found of the leather.	l on the flesh side			
	(f)	part of the si	kin is the lowest			
	(g)	English size 8 is equented paris point size				
	(h)	Area of parallelogram ,				
	(i)	Leather can be sorted on variation, thickness	the basis of color variation and			
	(j)	variation bas In nubuck leather on the surface.				

- Explain the graphical method and its demerits. 8 2. 3. What are the main characteristics of split/suede 8 leather? Explain. 4. Draw the diagram of hide/skin and show different 8 quality parts/regions on it. How you will calculate the scale area in RSM 5. 8 costing? 8 What are the defects of leather, explain? 6. Write short notes on the following: 6x5 = 307. Importance of work ticket. (a) (b) Common faults during cutting. (c) Demerits of tracing/layout method. (d) Show boards or Demo boards (e) Health and safety in the workshop.
- 8. What do you understand by planning? How planning can improve the productivity in cutting room, explain?

20

#### OR

How the synthetic materials are different from leather? How you will calculate the area requirement of synthetic material for certain number of pairs?

# जूते की अपर की कटिंग में प्रमाण-पत्र सत्रांत परीक्षा दिसंबर, 2011

ओ.ई.टी. - 012 : सामग्री लागत-निर्धारण एवं कटिंग

समय : 2 घण्टे			अधिकतम अंक :100		
<b>नोट : सभी</b> प्रश्नों के उत्तर देना <b>अनिवार्य</b> हैं।					
1.	रिक्त	स्थानों की पूर्ति करें :	1×10=10		
	(a)	बकरे के चमड़े की कटिंग से पूर्व करानी चाहिए।	मैचिंग		
	(b)	सामान्यतःके लिये 15 r दिया जाता है।	nm का प्रावधान		
	(c)	चमड़े के दोषों को मार्जिन में लिया जा सक			
•	(d)	कोटेड फैबरिक को सामान्यतः जाना जाता है।	नाम से		
	(e)	दोष चमड़े की फ्लेश जाता है।	साइड पर पाया		
	(f)	भाग खालों का सबसे व है।	मजोर भाग होता		

	(g)	के बराबर होता है।	
	(h)	समान्तर चतुर्भुज का क्षेत्रफल	
		=X	
	(i)	चमड़े की छँटाई, रंग में अन्तर, मोटेपन में अन्तर और अन्तर के आधार पर की जा सकती है।	
	(j)	न्यूबक चमड़े मेंप्रभाव सतह पर पाया जाता है।	
2.	ग्राफि कीजि	कल विधि को समझाइए और इस विधि के दोषों का वर्णन तए।	8
3.	स्पिति	लट/श्वेड चमड़े की प्रमुख विशेषताएँ क्या है, समझाइए।	8
4.		/स्किन का चित्र बनाइए और इसके विभिन्न गुणवत्ता भागों को दर्शाइए।	8
5.		एस.एम. मूल्यांकन विधि में आप स्केल क्षेत्रफल की गणना प्रकार करेंगे ?	8
6.	चमड़े	इ में पाए जाने वाले दोष क्या हैं, वर्णन कीजिए।	8

**OET-012** 

P.T.O.

7. निम्नलिखित पर संक्षिप्त टिप्पणी कीजिए :

6x5 = 30

- (a) वर्क टिकट का महत्व
- (b) कटिंग के दौरान सामान्य गलतियाँ
- (c) लेआउट/ट्रेसिंग विधि की कमियाँ
- (d) शो बोर्ड या डेमो बोर्ड
- (e) वर्कशॉप में स्वास्थ्य और सुरक्षा
- 8. योजना से आपका क्या अभिप्राय है? योजना किस प्रकार से 20 कटिंग विभाग की उत्पादकता में सुधार ला सकती है, समझाइए।

#### अथवा

सिन्थेटिक पदार्थ चमड़े से किस प्रकार से अलग है? आप किस प्रकार से कुछ जोड़ी जूतों के लिये सिन्थेटिक पदार्थ की आवश्यकता की गणना करेंगे?