No. of Printed Pages: 4

BFW-038

B.Sc. FOOTWEAR TECHNOLOGY (BSCFWT)

Term-End Examination June, 2014

BFW-038: INTRODUCTION TO MANUFACTURING TECHNIQUE

Time: 3 hours

Maximum Marks: 70

Note: Answer all questions.

SECTION A

- 1. Explain in brief: (Answer any *five* parts) $5 \times 3 = 15$
 - (a) What is the use of Aluminium strike plate?
 - (b) What are the methods of making clicking dies? Explain.
 - (c) How do we set the clicking press to operate it?
 - (d) Why are two buttons given to push to operate the clicking press?
 - (e) Draw the diagram of CPE 5 and CPE 7 and show cutting direction.
 - (f) Why are synthetic materials cut in layers? Explain.
 - (g) Why is a gap of minimum 2 mm given for cutting synthetic materials in layers? Explain.

SECTION B

2. Answer any *two* of the following:

2×5=10

- (a) What are the safety points one should remember while operating Bench Grinder?
- (b) Explain different types of clicking dies and their application.
- (c) List names of all the parts of clicking press and specify their functions.

SECTION C (Closing)

3.	(a)	Name and explain different types of Ancillary machines used in Closing Department.					
	(b)	Name and explain the types of tools used in Closing Department.					
	(c)	Explain the following terms : $1 \times 10 = 10$					
		(i) Punches					
		(ii) Pulley					
		(iii) Polypropylene Board					
		(iv) Shuttle					
		(v) Shaft					
		(vi) Head Groove					
		(vii) Hexagonal					
		(viii) Knee Press					
		(ix) Face Plate					
		(v) Throat Plate					

SECTION D

4.	(a)	Differentiate between metatarsals and						
		phalang	es.					5
	(b)	Explain the Thong Last.						
	(c)	Define	Meane	Forme	and	explair	n its	}
		importance during shoe making.						