No. of Printed Pages: 8

OET-011

CERTIFICATE IN SHOE UPPER CUTTING

00800

Term-End Examination
June, 2010

OET-011 : SHOE UPPER CUTTING PROCESS

Tim	ie : 3 h	nours Maximum Ma	Maximum Marks : 100			
Note: All questions are compulsory.						
1.	Fill in the blanks: 10x		10x1=10			
	(a)	The English size stick begins with zero inches.	at			
	(b)	Leather is permanently preserved form Hide/Skin produced by	of			
	(c)	Fabrics are classified as woven, non - wov and	en			
	(d)	Cutting Value (C.V.) = 100 – %	•			
	(e)	One sq.ft. = sq.dm.				
	(f)	Normally mm underl allowance is given.	ay			
	(g)	We always cut leather pa	ir-			

1

(h) Nubuck leather is made Ve				ide Velvetty by			
	(i) curve blades are used for cutting paper.						
	(j) Normally mm die is used for cutting upper and lining leather.						
2.	Match the following:			10x1=10			
		Column A		Column B			
	(a)	Oxford	(i)	4-5 mm			
	(b)	Paris Point	(ii)	3 and 4 quality area			
	(c)	Vegetable Tanning	(iii)	Pressure control			
	(d)	Poromeric	(iv)	Table-Run			
	(e)	Flay cut	(v)	Babool Bark			
	(f)	Folding Allowance	(vi)	Upto 3% defective area			
	(g)	Belly	(vii)	French size system			
	(h)	A-grade leather	(viii)	Synthetic material			
	(i)	Potentiometer	(ix)	Leather defect			
	(j)	Leather Grading	(x)	Vamp over quarter			

- 3. State True (T) or False (F) in the following: 10x1=10
 - (a) Tarsus consists of seven bones that forms the back of the foot.

- (b) French size begins with zero at 4 inches.
- (c) Hide/Skin at the end of post tanning operation are called Wet-Blue.
- (d) Cutting value is the % defective area of leather.
- (e) Leather is a natural product.
- (f) Flank is the most inferior part as per quality of leather.
- (g) Side is half of hide.
- (h) Zug-grain is corrected Grain leather.
- (i) Shallow curve blades are used to cut insole board.
- (j) Brand Mark is a man-made defect.
- 4. Give short answer to any (5) of the following: $5\times10=50$
 - (a) Draw a figure of goat skin and show different quality areas and their name.
 - (b) Explain anatomical structure of Hide/Skin.
 - (c) Briefly explain pre-tanning operations.
 - (d) Explain different types of fabrics used in shoe.
 - (e) What are the methods of leather grading followed in tannery? Explain.
 - (f) Briefly explain the types of leather defects.
 - (g) What are different types of dies used for machine cutting? Explain.

- 5. Attempt *any one* of the following:
 - (a) Explain parts of shoe and various materials used for shoe making.

1x20=20

- (b) Explain different methods used during physical testing of leather.
- (c) Explain the steps in setting and operating the Swing Arm Clicking Press.

ओ.ई.टी.-011

जूते की अपर की कटिंग में प्रमाण-पत्र सत्रांत परीक्षा जून, 2010

ओ.ई.टी.-011 : जूते के अपर को काटने का प्रक्रम

समय : ३ घण्टे			अधिकतम अंक : 100			
नोट : सभी प्रश्नों के उत्तर देना अनिवार्य है।						
1.	रिक्त	स्थानों की पूर्ति कीजिए :	10x1=10			
	(a)	अँग्रेजी साइज पद्धति में शून्य साइज से शुरू होता है।	इंच			
	(b)	चमड़े का स्थायी रूप में परिरक्षण, हार	इड /स्कीन की			
	(c)	जूते में इस्तेमाल होने वाले कपड़े को बु				
	(d)	कटिंग वैल्यू (सी.वी.) = 100-% _	-			
	(e)	एक वर्ग फुट = वर्ग डेस	नी मीटर।			
	(f)	दबाव मार्जिन मि.मी. हो	ता है।			
	(g)	चमड़े की कटाई हमेशा जाता है।	जोड़ी से किया			

- (h) न्युबुक चमड़े को _____ द्वारा वेलवेटी बनाया जाता हैं।
- i) कागज़ अथवा पतले चमड़े को काटने के लिए _____ कर्व ब्लेड का उपयोग किया जाता है।
- (j) अपर और लाइनिंग की कटाई में प्राय: _____ मि.मी. की डाई का इस्तेमाल करते हैं।
- 2. निम्नलिखित का मिलान करें:

10x1=10

	कॉलम अ		कॉलम ब
(a)	ऑक्सफोर्ड	(i)	_{4 - 5} मि.मी.
(b)	पेरिस प्वाइंट	(ii)	$_3$ और $_4$ गुणवत्ता क्षेत्र
(c)	वेजिटेबल टैनिंग	(iii)	दबाव नियंत्रक
(d)	पोरोमिरिक '	(iv)	टेबल रन
(e)	फ्ले-कट	(v)	बबूल के पेड़ की छाल
(f)	फोल्डिंग मार्जिन	(vi)	_{3%} तक दोषपूर्ण क्षेत्र
(g)	बेली	(vii)	फ्रेंच साइज पद्धति
(h)	ए-ग्रेड का चमड़ा	(viii)	सिंथेटिक सामग्री
(i)	पोटेंशियोमीटर	(ix)	चमड़े में दोष
(j)	चमड़े की ग्रेडिंग	(x)	क्वार्टर के ऊपर वैम्प

- 3. निम्नलिखित में **सही** अथवा **गलत** का चुनाव करे : 10x1=10
 - (a) टारसस में सात हिड्डयाँ होती हैं जो पैर का पिछला भाग बनाती हैं।
 - (b) फ्रेंच साइज पद्धित में शून्य 4 इंच से शुरू है।
 - (c) हाइड/स्कीन, पोस्ट टैनिंग प्रक्रिया के समाप्त होने पर वेट-ब्लू कहलाते हैं।
 - (d) चमड़े में % दोषपूर्ण क्षेत्र कटिंग वैल्यू कहलाता है।
 - (e) चमड़ा एक प्राकृतिक उत्पाद है।
 - (f) गुणवत्ता के हिसाब से फ्लैंक सबसे खराब क्षेत्र माना जाता है।
 - (g) हाइड के आधे भाग को साइड कहते है।
 - (h) जग-ग्रेन एक करेक्टेड ग्रेन चमड़ा है।
 - (i) इनसोल बोर्ड को काटने के लिए शैलो कर्व ब्लेड का इस्तेमाल करते हैं।
 - (j) ब्रांड मार्क एक मानव निर्मित दोष है।
- निम्नलिखित में से किन्हीं पाँच प्रश्नों का संक्षिप्त उत्तर लिखें : 5x10=50
 - (a) बकरे की खाल का चित्र बनाएँ तथा उसमें विभिन्न गुणवत्ता क्षेत्रों एवं उनके नामों को दर्शाएँ।
 - (b) हाइड अथवा स्कीन के एनाटोमिकल संरचना की व्याख्या करें।

- (c) प्री-टैनिंग प्रक्रिया की संक्षिप्त व्याख्या करें।
- (d) जूते में इस्तेमाल होने वाले विभिन्न प्रकार के कपड़ों का वर्णन करें।
- (e) टैनरी में लेदर ग्रेडिंग के लिए कौन सी विधियों का इस्तेमाल किया जाता है? वर्णन करें।
- (f) चमड़े में दोषों का वर्णन करें।
- (g) मशीन द्वारा कटाई के लिए इस्तेमाल होने वाली कौन सी विभिन्न डाइयाँ होती हैं? वर्णन करें।
- 5. निम्नलिखित में से **किसी एक** का उत्तर लिखें : 1x20=20
 - (a) जूते के भाग तथा जूता बनाने में इस्तेमाल होने वाले विभिन्न सामग्री का वर्णन करें।
 - (b) चमड़े के भौतिक जाँच में इस्तेमाल होने वाली विभिन्न विधियों का वर्णन करें।
 - (c) स्वींग आर्म क्लिकिंग प्रेस को सेट करने तथा चलाने के नियमों का क्रमवार वर्णन करें।